

Munich Motor Works

Independent BMW & MINI Servicing Specialists

Tel: 04-347 4666

email: mmw@eim.ae

Fax: 04-347 4676

website: www.munichmotorworks.ae



ESTIMATE

Mr Alexey Ozorishin

0567383610

Estimate Number: **125088**

Account Number: Ozo001

Order Ref:

Estimate Date: 19/04/2015

Estimate Valid to : 18/06/2015

Page Number: 1

| Plate Number | Make & Model | Chassis Number | Model Year | KM |
|--------------|-----------------|-------------------|------------|----|
| 24209 | PORSCHE CAYENNE | WP1ZZZ9PZ9LA65033 | | 1 |

1. Check what service is needed.
2. Check condition of all bulb(fog light message is showing)
3. Check condition of battery & charging of alternator car starting issue.
note: after car is driven for along time,(engine is hot already) when he switch off the ignition then try again to start, no response at all and no light from cluster either.
4. Carry out safety check.

| Description | Qty | Unit Price | Price |
|--|-----|------------|-----------------|
| Carry out engine oil service (minor) | 14 | 24.00 | 336.00 |
| Replacing original battery (bad health cell reading) <i>note: after replacing need further checking for the starter motor</i> | 6 | 24.00 | 144.00 |
| Replacing front lhs fog light bulb (busted) | 7 | 24.00 | 168.00 |
| Replacing heat exchanger gasket (badly leaking oil) | 15 | 24.00 | 360.00 |
| Replacing vacuum gasket (badly leaking oil) | 6 | 24.00 | 144.00 |
| Replacing vacuum pipe (booster to pump) badly broken air leaks NOT SAFE | 12 | 24.00 | 288.00 |
| NOTE: OTHER ITEMS LSO FOUND WHILE CHECKING (safety check) | | | |
| - upper control arm assembly (badly split rubber) | | | |
| - lower control arm assembly (badly split rubber) | | | |
| - engine mounting (slightly cracked rubber & weak) | | | |
| - front differential bushings (slight cracked rubber & weak) | | | |
| - wiper blades set (worn out), front & rear | | | |
| Labour Sub Total | | | 1,440.00 |

| Parts description | Qty | Unit Price | Price |
|------------------------|-----|------------|----------------|
| fully synthetic oil 1L | 8 | 58.00 | 464.00 |
| oil filter | 1 | 166.00 | Less 5% 157.70 |

Munich Motor Works

Independent BMW & MINI Servicing Specialists

Tel: 04-347 4666

email: mmw@eim.ae

Fax: 04-347 4676

website: www.munichmotorworks.ae



DINAN
performance without sacrifice
AUTHORIZED DEALER

ESTIMATE

Mr Alexey Ozorishin

0567383610

Estimate Number: **125088**

Account Number: Ozo001

Order Ref:

Estimate Date: 19/04/2015

Estimate Valid to : 18/06/2015

Page Number: 2

| Plate Number | Make & Model | Chassis Number | Model Year | KM |
|--------------|-----------------|-------------------|------------|----|
| 24209 | PORSCHE CAYENNE | WP1ZZZ9PZ9LA65033 | | 1 |

| Description | Qty | Unit Price | Discount | Total Price |
|-----------------------------------|-----|------------|----------|-----------------|
| air filter | 2 | 175.00 | Less 5% | 332.50 |
| ac filter | 1 | 185.00 | Less 5% | 175.75 |
| original battery | 1 | 1,000.00 | Less 5% | 950.00 |
| front fog light bulb | 1 | 188.00 | Less 5% | 178.60 |
| heat exchanger gaskets set | 2 | 90.00 | Less 5% | 171.00 |
| vacuum gaskets set | 4 | 20.00 | Less 5% | 76.00 |
| vacuum pipe booster to pump,big | 2 | 173.00 | Less 5% | 328.70 |
| vacuum pipe booster to pump,small | 2 | 173.00 | Less 5% | 328.70 |
| Parts Sub Total | | | | 3,162.95 |

I agree to pay for all work and parts required for the repairs described above at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. Any additional work found to be necessary must be authorised by myself prior to commencement. All goods shall remain the property of the seller until paid for in full. I have read and accept your terms and conditions.

Nothing herein is designed to nor will it affect a customers statutory rights

Signed _____ Date _____

LABOUR & PARTS 4,602.95

ESTIMATE TOTAL 4,602.95

Information relating to this Estimate